

December 5, 2023

Re: Important Safety Notice – Owner’s Manual Update for Certain Pointer Field TEK Semi Auto Shotguns

Legacy Sports International, Inc. recently learned of a potential safety issue related to an owner’s manual update for certain Pointer Field TEK Semi Auto shotguns sold after January 1, 2021. Specifically, certain Pointer Field TEK Semi Auto shotguns were shipped with an outdated version of the owner’s manual after modifications were made to the design of this firearm by the manufacturer. These firearms are safe to operate with proper assembly.

The only Pointer Field TEK Semi Auto shotguns affected by this advisory are those in the following sequential **FT Serial Number Range: 21FT-02576 thru 21FT-11005**



Location of Serial Number on Pointer FT 1

If you own a Pointer Field TEK Semi Auto shotgun between any of the above serial number ranges, we highly encourage you download the updated owner’s manual for the firearm at www.LegacySports.com/SafetyNotice. Alternatively, you can contact us by email at customerservice@legacysports.com, by phone at +1-755- 828-0555 (Monday through Friday, from 7:00 am to 4:00 pm Pacific Time), or by mail at Legacy Sports International, Inc., 4674 Aircenter Cir, Reno, NV 89502. Please make sure to include the serial number of your Pointer Field TEK Semi Auto shotgun, which is located on the left side of the shotgun, above the trigger guard.

Should you contact us, and we confirm that your shotgun is included in the safety notice, we will email or mail you the correct owner’s manual, free of charge. This is NOT A RECALL, so do not send us your shotgun.

We appreciate your assistance and apologize for any inconvenience this may cause you. Thank you for your patience and cooperation.

**** Pointer Field TEK Semi Auto shotguns that have been modified by the manufacturer will fall into the above serial number range and will have a contra nut that must be assembled by the operator, as seen below.****

ATTENTION!!! Before mounting the forearm do not forget to screw the contra nut onto the front of the magazine tube (Figure 3a). Failure to assemble the contra nut can result in serious damage to the firearm!!!



Figure 3a